

---

Subject: Changes in Output Z

Posted by [Steve](#) on Sat, 18 Jun 2005 14:42:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Guys,I think one problem overlooked with SETs (and I make them) off the top of my head is the huge change in output Z. This can easily be an 8 to one ratio, or more. As an example, the damping factor changing from 8 to just 1 over a portion of the cycle. So the control the amp has over the driver is constantly changing.PP can also have this problem, in a different way, though to a lesser extent.Take care.Steve

---