Subject: Re: Audio Note power transformer Posted by Wayne Parham on Tue, 22 Apr 2008 18:18:45 GMT

View Forum Message <> Reply to Message

Thanks for the advice. Let me see if I understand what you are saying: Changing core lamination material makes more difference than minor conductor size changes because of magnetic loss. Better to use M6 material than M19, either replace the laminations or build a new transformer with M6 core. Is that what you're saying?