
Subject: Re: linn, Direct Drive, homebuilds
Posted by [DRCope](#) on Wed, 28 Apr 2004 12:22:12 GMT
[View Forum Message](#) <> [Reply to Message](#)

Nope, none of the differences are due to phase issues. This is something I've heard consistently on all kinds of tables in all kinds of systems over the last 25+ years.
