

---

Subject: Re: AR Pulley

Posted by [martinleewin](#) on Thu, 24 Jun 2004 15:14:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanx Wayne,I found Joel @ The Turntable Factory. He is sending one "for a favor to be returned later" maybe Scott amp & tuner restoration work I do. The dimensions confirm the problem was a 50 Hz pulley.Martin W.

---