
Subject: Bad connection in arm of Dual 601 Turntable

Posted by [Harry van Iersel](#) on Thu, 18 Nov 2004 09:53:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

Dual 601 with Digitac 300 SE cartridge (equivalent to Dual M20E). One channel gives a poor output; I cleaned the contacts inside the tone arm; it helps for a day or so and then the channel is out or poor again. I would like to solder the connection but that's not simple. Any suggestions?
Harry
