

---

Subject: Re: Old Dual with motor problems  
Posted by [Wayne Parham](#) on Sun, 06 Feb 2005 20:38:35 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Sounds like the bearing is shot and it's seizing up. The hotter it gets, the more it'll grab.

---