

---

Subject: Re: Turntable thrust bearing (replacement) alternative

Posted by [Daave](#) on Fri, 04 Mar 2005 19:49:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Dan-Some corrosion on the post that the cueing cam assembly rotates on was preventing it from freely turning-so the catch lever would never "lock" into the ON position. Cleaning that up, removing all of the old grease that I could find got the ole LAB 80 running again. Now if I could just get the adjustment of the Eccentric screw on bottom correct to make it turn OFF when the arm gets to the middle of a record on "Manual" play!!! Garrard engineers really made things complicated-must have all been mechanical engineers!Cheers-Dave

---