

---

Subject: Re: Dual CS508 Sounds terrible  
Posted by [Manualblock](#) on Tue, 02 Aug 2005 08:24:28 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

You have to use a stethoscope and place the bell end right on the sub-chassis to see if the bearing is making noise when you spin it.

---