## Subject: Re: HELP with my Acoustic Research XA! Posted by BillEpstein on Mon, 08 Aug 2005 21:06:26 GMT View Forum Message <> Reply to Message

If you remove the bottom cover you will find there is a solder terminal where the spider thin strands of wire from the cartridge/arm connect to the output cable. They are very fragile!There is neutral and hot just like at the cartridge pins for each channel plus a separate ground. I recall then being color-coded like the cartridge but I'm not certain.You may have a partial short to ground on the bad channel so resoldering those leads might help. In any case, further help is available fron DDarch at Vinyl Nirvana or The Analog Dept The Analog Dept

Page 1 of 1 ---- Generated from AudioRoundTable.com