
Subject: Re: HELP with my Acoustic Research XA!

Posted by [hurdy_gurdyman](#) on Wed, 10 Aug 2005 21:40:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

Another place to check for wiring problems on the AR is where the wire runs between the top plate and the sprung subchassis. If the table was transported with the outer platter in place, the floating chassis will bounce around and chew through the wire. A complete tonearm rewiring is in order. Not hard, but requires patience. The AR-XA is worth the effort, IMHO.Dave
