

---

Subject: Re: Speed too fast

Posted by [Mike](#) on Tue, 22 Nov 2005 03:21:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

ah...forget it. i figured out the problem. the belt was wrapped too high around the platter and the belt kept slipping halfway off the spindle.

---