
Subject: Automatic Reject rejects too soon. Fisher MT-6630

Posted by [Tore](#) on Wed, 07 Dec 2005 11:54:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hey,I'd appreciate some help with this little problem. My Fisher MT-6630 turntable has a problem with the automatic reject system. At the end of the record it is supposed to lift the arm up and back again _after_ all of the music has been played, but instead it lifts before that happens. And since there is a delay from the time the automatic reject begins to the point where it lifts the arm, the record goes into a brief loop before this occurs. Painful to the ears and for the heart. It does not always occur on LP's but always on 7".Any ideas on fixing this?cheers, Tore
