

---

Subject: Re: jvc produces no sound

Posted by [Wayne Parham](#) on Wed, 01 Feb 2006 14:51:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Very true. If a turntable is plugged into an un-equalized (non-phono) input, the sound will be very tinny because of the RIAA curve. But if a magnetic cartridge is plugged into a ceramic input, the RIAA curve will already be applied. It will just need more gain.

---