

---

Subject: Re: Elac Miracord 50 H II  
Posted by [Wayne Parham](#) on Tue, 21 Feb 2006 19:08:50 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Look for a hydraulic damper. The damper is probably shot so replace it.

---