

---

Subject: NAD turntable

Posted by [Stuart.G](#) on Sat, 06 May 2006 00:20:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Dampening fluid has leaked from my NAD 5120 turntable (early 1990s model) during interstate transport. I've looked everywhere in Australia for more. Can't find any. Does anybody know where I can find some? What is the right viscosity for this particular dampening fluid? Appreciate any advice. Thanks. Stuart G.

---