
Subject: Re: Technics 1200 Output Problem
Posted by [Manualblock](#) on Tue, 09 May 2006 11:17:23 GMT
[View Forum Message](#) <> [Reply to Message](#)

Probably loose cartridge pins. It's pretty rare that wire inside the arm is defective. But think of this; if you are getting continuity from the table to the RCA plug then the signal should be getting through. At this point there is not much that you can check on the table; try checking the continuity from the cartridge pins to the RCA plug one at a time.
