

---

Subject: Re: Technics 1200 Output Problem  
Posted by [Mention](#) on Wed, 10 May 2006 04:31:51 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Found the problem. One of the wires going from the tone arm into the base had somehow been cut in half. It was sticking out from under the tone arm, I dont know how I had missed it before.  
Thanks.

---