Subject: thorens td160 tonearm problem Posted by kpl on Sun, 14 May 2006 07:20:01 GMT View Forum Message <> Reply to Message

Cleaned and oiled my TD160 turntable arm but anti bias adjuster no longer effective. Arm seems to be over biased even with the adjuster completely turned down(using the tracking ability test on record, the sound is like when the bias value has been set too high with the distortion in the left channel). Would appreciate any advice, suggestions, etc.

Page 1 of 1 ---- Generated from AudioRoundTable.com