

---

Subject: Goldring 1042 troubles

Posted by [Alex](#) on Tue, 01 Aug 2006 10:11:09 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a new model P3/RB300 set-up on 640p phono amp. I just bought a Goldring 1042 with about 30 hours on it to replace my well used Goldring Elektra. First mounted it quite forward, but after some remeasurement moved it back in the headshell. First impressions are mixed. Its very detailed, but seems lacking in any bass weight and sounds hissier than the Elektra. Any suggestions? Thanks, Alex.

---