

---

Subject: Re: turntable buzz (grounding)

Posted by [Bill Epstein](#) on Sun, 10 Sep 2006 23:13:35 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You always hear about "Grado hum" and unshielded TT motors are a problem. But you describe static, not AC hum. ISTM that what you have is the need to change the grounding set-up of table, cartridge and arm. Is the table grounded or are you only using the ground on the cables? Add a ground from table chassis to either the phono ground or another component. The beatings will continue until morale improves

---