

---

Subject: Re: turntable buzz (grounding)

Posted by [Russellc](#) on Sat, 16 Sep 2006 14:53:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Grados are unshielded, and if your motor is also unshielded, it can pick up hum from the motor. sometimes it increases as the arm moves closer to the motor. Russellc

---