
Subject: Re: Yamaha YP-B2 Needle drops too far into record
Posted by [Wayne Parham](#) on Fri, 22 Dec 2006 15:12:27 GMT
[View Forum Message](#) <> [Reply to Message](#)

I've never looked at your turntable, but most auto-set/auto-return tone arm drops are damped by a hydraulic cylinder. If yours drops rapidly, the damper is probably bad.
