
Subject: Re: Two turntables, two problems

Posted by [hurdy_gurdyman](#) on Thu, 28 Dec 2006 20:42:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

Sounds like a new belt would take care of the speed problem. The tracking force of the tonearm should either have a dial on the pivot structure and/or the counter-weight should be adjustable, probably by rotating it. Most Duals had both.

<http://www.compassnet.com/concept/tables/CS415-2.htm><http://www.compassnet.com/concept/tables/cs410.htm><http://www.dual-reference.com/Dave>
