

---

Subject: Re: Turntable buzz

Posted by [Wayne Parham](#) on Wed, 23 Jan 2008 14:39:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sounds like a bad connection on one of the leads. I think you're looking in the right places. I would replace the crimp connectors or at least solder the ones that are there. Might re-run or replace the wires through the tone arm.

---