

---

Subject: Re: Philco turntable hum

Posted by [Wayne Parham](#) on Thu, 17 Jul 2008 16:52:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If this is an old console system with tubes, more than likely the power supply filter capacitors are bad. They're easy to identify and replace, physically large and easy to spot. Just replace them with equal value or larger capacitors. They're probably values like 20uF or 33uF. Replace them with 250v or 400v polypropylene caps and they'll last a lifetime.

---