

---

Subject: Re: Pioneer RT - 707 woes (wows)

Posted by [Wayne Parham](#) on Fri, 03 Feb 2006 20:17:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You need a speed adjustment, and you may also need a pinch roller. It's possible you may need a motor or two. If you're comfortable working on the deck, pick up a service manual at [StereoManuals.com](#) and perform the adjustments prescribed. Pinch rollers were still available from Pioneer last time I checked, which was about two years ago. Mine had become jelly bears, so I bought a new one and a couple extras to keep on hand.

---