
Subject: Re: Marantz PMD220 RCA line out problem
Posted by [Wayne Parham](#) on Tue, 20 Jun 2006 20:50:47 GMT
[View Forum Message](#) <> [Reply to Message](#)

The connector might be fatigued or worn out. That's one of the problems with RCA connectors - the inner connection sometimes stresses and expands on the female and the outer sometimes does on the male. But they're inexpensive enough to replace.
