

---

Subject: Re: Sony TC-650

Posted by [slbender](#) on Fri, 13 Apr 2007 23:46:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi - In any 30 y/o set with permalloy heads, this could be one of ten different things, worn head, capacitor problem, internal controls, alignment, tough to guess. I have most of the remains of a TC-650, probably including a head block.-Steven

---