

---

Subject: Re: Stuffing thickness

Posted by [Manualblock](#) on Fri, 13 Aug 2004 00:20:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Bill; When you say full; How would you determine the exact amount of stuffing and is placement critical along the line? Or do you stuff the line to a certain density and that will address the nodes? Is there a specific density required of the material itself that is optimal for this application? Thanks, J.R.

---