

---

Subject: Re: response graph

Posted by [hurdy\\_gurdyman](#) on Thu, 26 May 2005 16:11:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'm trying to track down the reason for a peak around 1200 Hz on my Avid 60's response. See them and the response graph at the bottom of the page here.[http://pg.photos.yahoo.com/ph/the\\_hurdy\\_gurdyman/album?.dir=6d5d&.src=ph&store=&prodid=&.done=http%3a//pg.photos.yahoo.com/ph/the\\_hurdy\\_gurdyman/my\\_photos](http://pg.photos.yahoo.com/ph/the_hurdy_gurdyman/album?.dir=6d5d&.src=ph&store=&prodid=&.done=http%3a//pg.photos.yahoo.com/ph/the_hurdy_gurdyman/my_photos)I'm open to suggestions on what is causing this and what the cure is. I don't know if this is a whizzer problem, box/grill problem, surround problem (not the factory surround) or something else altogether. Maybe a notch filter, or perhaps dammar varnish on the whizzer? Open to anything right now. Still love the way these sound and image, but there is always room for improvement.

---