
Subject: Re: Horn throat size

Posted by [Mike.e](#) on Sat, 21 Aug 2004 06:15:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

Compression ratio is regarded as being safe at 2:1 but after 3:1 problems can easily occur with loudspeaker cones. The mcbear program will show you responses but won't tell you if distortion will result from your miniature too small horn throat. But with a little knowledge applied to the program, meaningful results happen. <http://www.volvotreter.de/> >downloads > dinsdale horn article http://www.volvotreter.de/downloads/Dinsdale_Horns_1.pdf
