

---

Subject: issue

Posted by [Mike.e](#) on Wed, 25 Aug 2004 03:57:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Is this a common occurrence? 'lightweight' or 'weak' higher Qts drivers in horns with high acoustic load end up with this problem? High compression ratio, high BL driver

---