

---

Subject: Re: first set of measurments

Posted by [Eric Mainardi](#) on Fri, 13 May 2005 14:51:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi TIM, This matches measurements I did a few months ago with my T350 from the late eighties. As they are ALNICO drivers, the slight loss of efficiency is probably due to loss of magnetization with age which is roughly around 3% per 10 year period for alnico. Very smooth and very sweet tweeter (phenolic diaphragm) ERIC

---