

---

Subject: Re: 50Hz - 200Hz

Posted by [Wayne Parham](#) on Mon, 30 Jan 2006 23:50:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

It's caused by flux modulation, making piston motion asymmetrical. A properly designed shorting ring helps counteract this.

---