
Subject: Re: Need help with room placement
Posted by [Wayne Parham](#) on Wed, 07 Jun 2006 19:30:08 GMT
[View Forum Message](#) <> [Reply to Message](#)

My gut feeling is that the difference is mostly due to the collapsing DI of the 811 as opposed to more uniform DI of the 2370. This causes a difference of HF energy in the reverberent field.
