

---

Subject: Re: Sprinkling posts...

Posted by [akhilesh](#) on Thu, 15 Jul 2004 23:23:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Robert, Maybe the driver cones absorbed some moisture and became "doped" in some way. I know a lot of builders dope them anyway. Just a hypothesis. -akhilesh

---