
Subject: Re: Newest acquisition 2 - 8" full range from Roland

Posted by [roncla](#) on Tue, 14 Sep 2004 21:09:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

If the throat of a horn ,which is little more than a flared TL, has zero area ($S_o=0$)then you will get excessive ripple in the FR curve no matter what the length. Bob's sim shows what happens.Look to the left of the page and click on Voight pipes and read what the results were.
[ronhttp://www.geocities.com/rbrines1](http://www.geocities.com/rbrines1)
