

---

Subject: Re: Newest acquisition 2 - 8" full range from Roland

Posted by [roncla](#) on Wed, 15 Sep 2004 21:59:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Must be my program as i see an increasing pressure at the top as the cone moves inward. Then i see an expanding pressure front from the pointed end which arrives at the port later in time than the driver point. Harmonic?ron

---