

---

Subject: Re: Isobaric

Posted by [lon](#) on Wed, 16 Feb 2005 03:37:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I started to cut wood today, but that wasn't the problem. I have not used the subwoofer out on the receiver before. Maybe someone in here can help with that. Is it true that the sub only kicks in at certain frequencies. Also, my setup instructions from the receiver show an RCA connection out of the Yam and into some sort of Yam sub. My question is: even if the connection to the outboard amp is necessary for whatever add-ons Yamahasells, should I not hear something out of the speakers? No info in the documentation. I'm going to have a friend bring his meter over here and see if he can get a reading. But nothing came through given I just did an alligatorclip connection on this wire. Could be the cheap plug I cut off was no good too. Lots of variables at that point. I did the battery test on the speakers and they are both okay. So maybe somebody can walk me through the troubleshooting. The plug is located just below all the input jacks and a tape out pair. The directions show a connection of RCA at both ends to connect the add-on Yamaha sub.

---