

---

Subject: Re: Isobaric

Posted by [lon](#) on Wed, 16 Feb 2005 21:35:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I just made the hookup to the little RS amp. I would say there is a problem from connecting the Yam to the tuner in on the amp. I had to jack the amp up to full volume to get any signal at the speakers. This cannot be right. Maybe I'd need the phono preamp connection to get any juice. But I'm not going to proceed until I know more. Your suggestion sounds right though and the RS should be the ideal unit without buying a new piece of gear. Maybe a y-connect from the subwoofer out on the Yam to the left right connects on the RS? I haven't tried the phono in to check this. What kind of damage can I do? I've already spent some dough on a repair guy to fix the RS (amp chip replacement) once for about the cost of what I paid for it. :-/

---