

---

Posted by [Wayne Parham](#) on Wed, 31 May 2006 14:49:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The tweeter is actually about a decibel lower than the midrange. It's barely audible but you can see it in the measurements. There's a gradual downward slope at the crossover region, drops a decibel around 5kHz. Other than that and a small 1dB suckout around 800Hz, response is basically a straight line.

---