
Subject: Re: Goodmans Update - Bass and Notch
Posted by [B.Arnstein](#) on Thu, 16 Aug 2007 03:53:02 GMT
[View Forum Message](#) <> [Reply to Message](#)

Many of the problems of severe notches in the response of thin coned speakers are caused by inappropriate cone manipulation causing creasing in the paper. Also fatigue problems at the cone apex will create a circular corrugation with a dip and peak characteristic.
