

---

Subject: Re: Line Array discussion

Posted by [jdybnis](#) on Tue, 07 Sep 2004 00:14:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Interesting. If I understand this correctly it implies that a typical 5" ribbon tweeter (single, not in an array) is going to suffer from these same problems operating in its normal range (>3000Hz).

---