
Subject: Re: Newform R30 / Scan 8545 array
Posted by [Eric](#) on Wed, 07 Feb 2007 15:06:34 GMT
[View Forum Message](#) <> [Reply to Message](#)

Have you checked the ground on the XLR's. I had low level noise issues with my cables runing past my tube preamp. I still don't know why.
