Subject: Re: so I built these lines with a single tweeter Posted by Anonymous on Sun, 27 Jan 2008 02:16:10 GMT

View Forum Message <> Reply to Message

NSB installation was a PITA. The frame lip problem. I used a precision rabbet after cutting the hole out, to recessthe frame lip inside it. Then I used generic rope caulk foundat partsexpress to gasket the driver.