Subject: No imagery

Posted by Tom Daugherty on Tue, 15 Jul 2008 04:36:46 GMT

View Forum Message <> Reply to Message

I'm new here and I think I need some help. I have a 2006 Tacoma and I installed an aftermarket system. Pioneer head unit, Art Kar 400.4 amp, RS125-4 for mids, Vifa XT25SC50-04, and an Aura amp for the sub. for the tweeters. I noticed that there is no imagery. The music is coming from the left side and the right side, nothing in the middle. The xo is active on the Art @ 2500hz and passive high pass on the mids at about 80hz. Could I have one of the speakers out of phase? Is there a way to check with out pulling the door panel? Thanks Tom