

---

Subject: Re: Philco model 41-280

Posted by [Wayne Parham](#) on Fri, 17 Sep 2004 17:18:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You can replace them with 250V polypropylene caps of the same capacitance value. I usually do that with most old tube radios, because the capacitors are almost always bad.

---