
Subject: Re: Montgomery Ward Airline console
Posted by [Wayne Parham](#) on Fri, 05 May 2006 04:00:25 GMT
[View Forum Message](#) <> [Reply to Message](#)

Sounds like you found a real bargain! Post a photo if you can. As for the imbalance, I'd probably replace the capacitors and see if that fixes it. If they haven't been replaced already, they're old enough they need to be. So that's a good place to start. Let us know how it works out.
