Subject: Re: Help with Grunow Model: 660 Chassis:6C Posted by Wayne Parham on Thu, 21 Sep 2006 14:05:19 GMT View Forum Message <> Reply to Message

Have you checked to make sure the potentiometer is connected properly? If wires to pins 1 and 3 are reversed, the volume knob works backwards like that.