
Subject: Re: Help with Grunow Model: 660 Chassis:6C
Posted by [Wayne Parham](#) on Fri, 22 Sep 2006 00:17:59 GMT
[View Forum Message](#) <> [Reply to Message](#)

One side of the potentiometer should probably be connected to ground, the other to a driver stage output and the wiper to the input of an amplifier stage.
